Assembly Diagram for Model FDS 10DVA



PARTS

FSD 10DVA

	ITEM NO.	CODE NO.	DESCRIPTION	NO. USED	REMARKS	
*	1		NAME PLATE	1		
	2	308-511	– DRIVER BIT 4MMX50L	1		
	3	310-794	HOUSING (A).(B) SET	1		
	4	309-614	TAPPING SCREW (W/FLANGE) D3X14	7		
	5	309-611	BIT HOLDER (B)	1		
	6	309-617	STRAP	1		
	7	980-838	FLAT HD. SCREW (LEFT HAND) M5X20	1		
	8	303-915	DRILL CHUCK 10TLRA – N (W/O CHUCK HANDLE)	1		
	9	309-599	CAP	1		
	10	309-600	SPRING HOLDER	1		
	11	309-601	SPRING	1		
	12	309-602	THRUST PLATE	1		
	13	309-604	SPINDLE AND GEAR SET	1		
	14	309-603	STEEL BALL	4		
	15	309-607	SHIFT ARM	1		
	16	309-606	TAPPING SCREW D3X8	4		
	17	309-608	SHIFT KNOB	1		
	18	309-609	SHIFT SPRING	1		
	19	309-612	BIT HOLDER (A)	1		
	20	308-510	+DRIVER BIT NO.2X50L	1		
	21	310-793	MORTOR	1		
	22	310-155	SWITCH (1P SOLDER TYPE)	1		
	22	310-795	SWITCH (1P SOLDER TYPE)	1	FOR EUROPE	
	23		DECORATION NAME PLATE	1		
	24		MARK PLATE	1		
	25		FT SCREW M3X10	1		
	26		FT SCREW M3.5X8	1		
	27	310-156	FIN ASS'Y	1	INCLUD.25,26	
	28	310-157	TERMINAL	1		
*	29	310-874	BATTERY FEB 9 (W/ENGLISH N.P.)	1		
*	29	310-767	BATTERY FEB 9 (W/ENGLISH N.P.)	1	FOR EUROPE	
*	29	310-766	BATTERY FEB 9 (W/ENGLISH N.P.)	1	FOR USA	

STANDARD ACCESSORIES

ITEM NO.	CODE NO.	DESCRIPTION	NO. USED	REMARKS	
501	309-926	CASE	1		
502		CHARGER (MODEL UC 9SC)	1		

* : ALTERNATIVE PARTS

Printed in Japan